

Instructions for use

Zeptide

(Tirzepatide)

Solution for Injection for Subcutaneous Use


2.5 mg 5 mg 7.5 mg 10 mg 12.5 mg 15 mg

For Single Dose Only




FEROZSONS
LABORATORIES LIMITED


Prefilled Syringe
Once Weekly




Take the Pre-Filled Syringe and needle out of the provided tray.




Hold the syringe in an upright position. Remove the luer lock by rotating it in the anti-clockwise (left) direction.




Keeping the Pre-Filled Syringe in an upright position, attach the needle to the body of the Syringe by rotating the needle in clockwise (right) direction and carefully pull off the needle cap before use.




To remove the air from syringe, push the plunger rod till a drop appears at the tip of the syringe.




Zeptide Pre-Filled Syringe may be injected at any site as shown in picture. Clean a small area of skin with an alcohol swab. Let the alcohol dry completely before you inject.



Hold the Pre-Filled Syringe like a pencil. Do not let the needle touch any surface. Pinch your skin and inject the needle completely into the skin fold at 45° or 90°.



Slowly push the plunger to inject Zeptide under the skin making sure all the tirzepatide has been injected. Hold the plunger for a few seconds.




Note:
* Do not reuse the PFS.
* The PFS must not be shared.


4000003479




سوی فیلڈ سرنج کو بائیں سے باہر نکالیں۔ پھرٹ کے پھوسنے سے انجیکشن والے مقام کو ہوا کر رکھیں۔ استعمال شدہ سرنج کو درست طریقے سے تباہ کریں۔




پنجر کو آہستہ سے دہانیں تاکہ ٹرزیپٹائیڈ کی پوری مقدار بائیں دہانوں میں پہنچانے۔ پنجر کو پھینک دیا کر رکھیں۔




پری فیلڈ سرنج کو پینٹیل کی طرح پھریں۔ سوی کو کسی اور جگہ نہ لٹھنیوں۔ جگہ کو اوپر کی طرف اچھالیں اور سوی کو ۳۵ یا ۹۰ درجے کے زاویے سے پورا بائیں دہانوں میں اتاریں۔




زیپٹائیڈ پری فیلڈ سرنج تصویر میں واضح کیے گئے کسی بھی مقام پر لگ سکتا ہے۔ انجیکشن لگانے والے مقام کو پھرٹ سے صاف کریں۔ انجیکشن لگانے سے پہلے پھرٹ کو مکمل سوکھنے دیں۔



سرنج سے ہوا نکلنے کے لیے پلنجر روڈ کو اتار دہانوں کو سوئی کی ٹوک پر ایک قطرہ نمودار ہو جائے۔



پری فیلڈ سرنج کو سبھا رکھتے ہوئے سوئی کو دہانیں چاہے گھما کر سرنج سے جوڑیں اور استعمال سے پہلے احتیاط سے سوئی کے ڈیکپ کو ہٹا دیں۔



سوئی کی پینک کو ہٹانے کیلئے گور کے ٹیپس کو محتاط ست میں چھیں۔



سرنج کو سبھا رکھیں۔ لوزلاک کو بائیں چاہے گھما کر رکھیں۔



پری فیلڈ سرنج اور سوئی کو دیگی ٹرے سے باہر نکالیں۔

پری فیلڈ سرنج
ٹھٹھے میں ایک مرتبہ

استعمال کرنے کی ہدایات
زیپٹائیڈ

ٹرزیپٹائیڈ (ٹرزیپٹائیڈ) سلوشن فار انجیکشن زیر جلد استعمال کیلئے

۵.۰۰۵ ملی لیٹر ۵.۰۰۵ ملی لیٹر ۵.۰۰۵ ملی لیٹر ۱۰.۰۱۰ ملی لیٹر ۱۰.۰۱۰ ملی لیٹر ۱۵.۰۱۵ ملی لیٹر



BIOSCIENCES

FEROZSONS
LABORATORIES LIMITED

4000003479